

HUAWEI Module

# **Upgrade Guide on Embedded Linux**

lssue 05 Date 2013-12-28 Huawei Technologies Co., Ltd. provides customers with comprehensive technical support and service. For any assistance, please contact our local office or company headquarters.

### Huawei Technologies Co., Ltd.

Huawei Industrial Base, Bantian, Longgang, Shenzhen 518129, People's Republic of China Tel: +86-755-28780808 Global Hotline: +86-755-28560808 Website: www.huawei.com E-mail: mobile@huawei.com

Please refer color and shape to product. Huawei reserves the right to make changes or improvements to any of the products without prior notice.

#### Copyright © Huawei Technologies Co., Ltd. 2013. All rights reserved.

No part of this document may be reproduced or transmitted in any form or by any means without prior written consent of Huawei Technologies Co., Ltd.

The product described in this manual may include copyrighted software of Huawei Technologies Co., Ltd. and possible licensors. Customers shall not in any manner reproduce, distribute, modify, decompile, disassemble, decrypt, extract, reverse engineer, lease, assign, or sublicense the said software, unless such restrictions are prohibited by applicable laws or such actions are approved by respective copyright holders under licenses.

#### Trademarks and Permissions

#### 

HUAWEI, HUAWEI, and Ware trademarks or registered trademarks of Huawei Technologies Co., Ltd. Other trademarks, product, service and company names mentioned are the property of their respective owners.

#### Notice

Some features of the product and its accessories described herein rely on the software installed, capacities and settings of local network, and may not be activated or may be limited by local network operators or network service providers, thus the descriptions herein may not exactly match the product or its accessories you purchase.

Huawei Technologies Co., Ltd. reserves the right to change or modify any information or specifications contained in this manual without prior notice or obligation.

#### **NO WARRANTY**

THE CONTENTS OF THIS MANUAL ARE PROVIDED "AS IS". EXCEPT AS REQUIRED BY APPLICABLE LAWS, NO WARRANTIES OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, ARE MADE IN RELATION TO THE ACCURACY, RELIABILITY OR CONTENTS OF THIS MANUAL.

TO THE MAXIMUM EXTENT PERMITTED BY APPLICABLE LAW, IN NO CASE SHALL HUAWEI TECHNOLOGIES CO., LTD. BE LIABLE FOR ANY SPECIAL, INCIDENTAL, INDIRECT, OR CONSEQUENTIAL DAMAGES, OR LOST PROFITS, BUSINESS, REVENUE, DATA, GOODWILL OR ANTICIPATED SAVINGS.

#### Import and Export Regulations

Customers shall comply with all applicable export or import laws and regulations and will obtain all necessary governmental permits and licenses in order to export, re-export or import the product mentioned in this manual including the software and technical data therein.



## **About This Document**

## **Revision History**

Document Version	Date	Chapter	Descriptions
01	2013-04-17		Creation
02	2013-07-18	1	Added the description about MIPS/X86
03	2013-07-27	1	Added the description about Chrome OS in NOTE
		2.1	Added the description about Chrome OS
04	2013-08-31	1	Added the description about Android OS
05	2013-12-28	1	Added Table 1-1 List of UpdateWizard tool version
		2.2	Updated Command List
		2.4.4	Added Table 2-1 Error code
		3.2	Deleted 3.2 How to Find the PCUI Port



## Contents

1 Introduction	5
2 Upgrade Guide	7
2.1 Ready for Update	7
2.2 Command List	7
2.3 Upgrade Procedures	8
2.4 Information Displaying	9
2.4.1 Step Information	9
2.4.2 Firmware Information	10
2.4.3 Download Progress	10
2.4.4 Error Code	11
2.4.5 Time Cost	12
3 FAQ	
3.1 When do You Need the Update Password	13



Huawei UpdateWizard for embedded Linux such as Android OS and Chrome OS is the tool which is just for updating the firmware of HUAWEI module.

The tool complies with interfaces of HUAWEI device and is forbidden to apply to devices of any other manufacturer.

The following rules must be observed for upgrading HUAWEI module:

- The tool is only applicable to the device based on MIPS/X86/ARM (Advanced RISC Machine) on embedded Linux system.
- You should not power off the module during the update process, otherwise it may cause much damage to the module.
- On Android OS, you should stop the ril process before upgrading HUAWEI module. [How to stop the ril process]: execute the command stop ril-daemon. Otherwise, use command ps rild to get the ril PID, then use kill 'PID' to kill the ril process.

#### 

- The full directory of the module's firmware package with ".BIN" format needs to be input when using the UpdateWizard tool.
- Input password if it is necessary (about when you need the password, please see section 3.1), as "-p password". Command rules: "full directory of the update tool" + "full directory of the module's firmware package" + "-p" + "password". For example: /data/Resources/UpdateWizard /data/Resources/11.103.10.00.00.BIN -p 47309592
- On Chrome OS, it is recommended to use the path /local/bin as the default upgrade tool directory.
- Do not run other program or process, and ensure PCUI port and Diag port are not occupied.

If the tool works, a log file **hwupgradewizard.log** will be created in the path as shown in Table 1-1.

Table 1-1	List of U	poatevvizard too	version	

Table 4.4 List of Lindots\//impad to all yoursian

Tool Version	OS	CPU	Additional Features	Log Path
V300R001B11 0SP01C03	Chrome/Linux	X86	VID: 0x12D1	./var/tmp



Introduction

Tool Version	OS	CPU	Additional Features	Log Path
V300R001B11 0SP02C03	Android/Linux	ARM	VID: 0x12D1	./var/tmp
V300R001B11 0SP03C03	Android/Linux	ARM	VID: 0x03F0	Working directory of UpdateWizard tool
V300R001B11 0SP05C03	Android/Linux	X86	VID: 0x12D1&0x03F0 (Supported MBIM)	Working directory of UpdateWizard tool
V300R001B11 0SP06C03	Android/Chro me/Linux	ARM& X86	VID: 0x12D1&0x03F0	Working directory of UpdateWizard tool



# **2** Upgrade Guide

## 2.1 Ready for Update

- According to the device's CPU architecture, choose the correct version of UpdateWizard tool (see Table 1-1).
- If the tool version you choose is V300R001B110SP01C03 or V300R001B110SP02C03, make sure that the path /var/tmp exists. If it does not exist, please create a "tmp" folder in the var directory.
- For using the UpdateWizard tool, you should let it in the place where the tool will work in. For example: choose the path /data/Resources on Android/Linux OS or the path /local/bin on Chrome OS.
- Run the command as **chmod 777** /data/Resources/UpdateWizard to make sure full control over the account level of the tool.

## 2.2 Command List

For example, choose the path **/data/Resources** as the default directory for UpgradeWizard tool.

- Step 1 Make sure that the PCUI port exists and no other tool or program occupies the PCUI port.
- Step 2 Check whether the module supports the bodySAR function or not. And then, perform one of the following:
  - 1) If the bodySAR function is supported, go to Step 3.
  - 2) If the bodySAR function is not supported, go to Step 4.
- Step 3 Check whether you need the update password or not (please see section 3.1 ). And then, perform one of the following:
  - 1) If the password is not needed, run the command /data/Resources/UpdateWizard /data/Resources/XXXX.BIN /BKBODYSAR to start updating.
  - 2) If the password is needed, run the command /data/Resources/UpdateWizard /data/Resources/XXXXX.BIN /BKBODYSAR -p XXXXXXXX to start updating.



- Step 4 Check whether you need the update password or not (please see section 3.1 ). And then, perform one of the following:
  - 1) If the password is not needed, run the command /data/Resources/UpdateWizard /data/Resources/XXXX.BIN to start updating.
  - 2) If the password is needed, run the command
     /data/Resources/UpdateWizard /data/Resources/XXXX.BIN -p
     XXXXXXXX to start updating.

#### 

- /data/Resources/UpdateWizard: the full directory of this tool.
- /data/Resources/XXXX.BIN: the full directory of the ".BIN" file.
- -p XXXXXXXX: the update password.
- **/BKBODYSAR**: back up bodySAR values before update, and restore bodySAR after update.
- The path for the update tool, ".BIN" files and parameters (command parameters or password) must be separated with a half-width space.

## 2.3 Upgrade Procedures

Step 1 Ensure that the interfaces of HUAWEI module can be displayed on embedded Linux system. (Some other modules may be displayed differently.)

<pre>root@localhost sdk]# cd /sys/bus/usb/drivers/option/ root@localhost option]# ls</pre>		
-1:1.0 1-1:1.1 1-1:1.2 1-1:1.3 1-1:1.4 bind module [root@localhost option]#	uevent	unbind

Step 2 Use command line **chmod 777 UpdateWizard** to get the update program execution permissions.

[root@localhost Update]# chmod 777 UpdateWizard

Step 3 Execute the upgrade program.

root@localhost Update]# ./UpdateWizard MU739update\_11.102.03.00.111.bin

Step 4 Run successfully.



EM_STATE_RESUME_	NV: resume nvFirmware Ver
on: 11.102.03.0	0.11
Last error: 0: 5	uccess
acpid: can't ope	n /proc/acpi/event: Device or resource busy
End Time: 14:36%	:20
Program takes	207 seconds.
[root@localhost	Update]# vim /var/tmp/hwupgradewizard.log

Step 5 Look over the log. (Take the log path "var/tmp" as an example.)



Step 6 Check the upgrade result by using the minicom tool of Linux system. Open the PCUI port, and send AT command **ATI** to confirm the current firmware version.

```
ATI
Manufacturer: Huawei Technologies Co., Ltd.
Model: MU739
Revision: 11.102.03.00.111
IMEI: 492100022000111
+GCAP: +CGSM
OK
```

## 2.4 Information Displaying

Because the UpdateWizard tool for embedded Linux does not work with UI, all of the information is output to the shell window, including step information, firmware information, download progress, error code and time cost.

#### 2.4.1 Step Information

Before operating every step, the tool will give some information to show what the tool is doing, as shown in the following figure.



# upd 111.BIN	
Start Time: 7:39:58	
EN STATE EINDING: begin search device	
CH_STATE_FINDING, begin search device	
The STATE CHECKINFU: begin check device information	
ISU Version: //	
Authority ID: 492100022000111	
Board Class: Huawei MU739	
Firmware Version: 11 102 01 02 00	
EN STATE PACKUD NV, beckup av	
EM_STATE_SWITCHPORT: switch port	
EM_STATE_UPDATING: updating	r
Now update progress percents: 1	
Now update progress percents: 2	
n	

### 2.4.2 Firmware Information

When the tool is in the step of "check device information", the device information will be output on the shell window after the update begins, as shown in the following figure.



#### 2.4.3 Download Progress

When the tool is downloading the data, it will show how much data has been downloaded, as shown in the following figure.

Now	update	progress	percents	. 50
Now	update	progress	percents	51
Now	update	progress	percents	52
Now	update	progress	percents	53
Now	update	progress	percents	54
Now	update	progress	percents	55
. Now	update	progress	percents:	56
Now	update	progress	percents	57
Now	update	progress	percents	58
Now	update	progress	percents	59
Now	update	progress	percents	60
Now	update	progress	percents	61



## 2.4.4 Error Code

Before the tool exits, it will show the last error code, as shown in the following figure.



#### Table 2-1 Error code

Error Code	Meaning	Simple Solution
0	Upgrade the module successfully.	-
10	Cannot find the upgrade port.	Check whether the module is working and its driver is loaded correctly or not.
11	Open the upgrade port unsuccessfully.	Check whether the PCUI port is occupied or not.
12	Query the download version of the module unsuccessfully.	Check whether the module is working or not.
13	Upgrade authentication failure	The module does not support the upgrade agreement.
14	Back up the NV data unsuccessfully.	Re-upgrade it again. If failed, it indicates the module does not support the upgrade agreement.
16	Change to the upgrade mode unsuccessfully.	It indicates the PCUI port is occupied or abnormal.
17	Verify the product ID unsuccessfully.	It indicates the module does not match with the upgrade package.
18	Verify the upgrade package unsuccessfully.	It indicates "./" is missed in the upgrade package directory, or it is the upgrade package CRC code error.
19	Upgrade the firmware package unsuccessfully.	It is an UpdateWizard tool error or a module error. Need HUAWEI's support.
20	Restart the module unsuccessfully.	It indicates the device does not support the restart command after upgrading or the PCUI port is missed.



Error Code	Meaning	Simple Solution
21	Restore the NV data unsuccessfully.	Need HUAWEI's support
30	UpdateWizard is running.	-
255	Unknown error	Reserved

## 2.4.5 Time Cost

The start time, end time and the time cost for the update will be displayed, as shown in the following figure.

Now update progress percents: Now update progress percents: EM_STATE_RESUME_NV: Firmware Version: 11.102.03.00	99 100 resume nv 0.111
Last error: 0: Success End Time: 7:55:59	
Program takes 217 seconds.	▶



# **3** FAQ

## 3.1 When do You Need the Update Password

There is a C version in the firmware version that indicates the customized or general version. C00 is the general version, and others are the customized version, just as shown in the following picture.

Revision: 11.103.15.00.00

In the following two cases, you need the update password.

- A customized version is updated to a general version. For example: the current module firmware version is C1103, and the firmware version being updated is C00.
- A customized version is updated to a different customized version. For example: the current module firmware version is C1103, and the firmware version being updated is C156.

The update password can be provided by HUAWEI.